Handout B

2017 FACILITY ASSESSMENT BOARD UPDATE





SCOPE OF WORK

NON-INVASIVE VISUAL ASSESSMENT AND ASSOCIATED REPORT FOR:

- BETTENDORF HIGH SCHOOL
- BETTENDORF MIDDLE SCHOOL
- EDISON ACADEMY
- HERBERT HOOVER ELEMENTARY SCHOOL
- MARK TWAIN ELEMENTARY SCHOOL
- PAUL NORTON ELEMENTARY SCHOOL
- THOMAS JEFFERSON ELEMENTARY SCHOOL

DID NOT INSPECT THE FOLLOWING:

- GRANT WOOD ELEMENTARY SCHOOL
- NEIL ARMSTRONG ELEMENTARY SCHOOL





TEAM CONFIGURATION



ASSESSMENT OF INTERIOR FINISHES, EXTERIOR BUILDING ENVELOPE AND ROOFS.



ASSESSMENT OF MECHANICAL, ELECTRICAL, PLUMBING, AND FIRE PROTECTION SYSTEMS.



ASSESSMENT OF EXTERIOR HARD SURFACES SUCH AS PARKING LOTS, SIDEWALKS, ETC.




INVESTIGATION OF POTENTIAL COSTS
RELATED IMPROVEMENTS INDICATED IN
REPORTS.





OVERVIEW OF PROCESS







FACILTY ASSESSMENT DELIVERABLE

Master Facility Plan - Estimates of Probable Cost * Bettendorf School District sustainability performance design									
FACILITY	Category	Capital Projects Strategy	CATEGORY	WORKITEM	Baseline MP 2016		Additional MP Work	Actual	NOTES
es not include	e asbestos abatement	I and annual District maintenan	I ice items	I	Funded	Unfunded	New Unfunded	Approved Scope	
Facilities	1	Building Envelope	Doors & Hardware	Remove and replace exterior frame & door	\$7,716				
Facilities	2	Building Envelope	Doors & Hardware	Replace Exterior Doors	\$11,574				
Facilities	1	Building Envelope	Masonry	Masonry Tuckpointing Allowance	\$12,860				
Facilities	1	Building Envelope	Masonry	Masonry Cleaning Allowance	\$3,215				
Facilities	1	Building Envelope	Roofing	Category 1 Roof Repair	\$3,215				
Facilities	1	Building Envelope	Roofing	Roof Area 1 - Shingle - Remove and Replace	\$13,191				
Facilities	1	Building Envelope	Roofing	Roof Area 2 - Flat Seam Copper	\$12,024				
Facilities	1	Building Envelope	Windows	Window Replacement	\$27,006				
Facilities	1	Building Systems	Electrical Distribution	Electrical Distribution Upgrades	\$3,215				
Facilities	1	Building Systems	Electrical Lighting		\$0				
Facilities	1	Building Systems	Fire Alarm	Fire Alarm: Upgrade A/Vs and initiating devices	\$0				
Facilities	1	Building Systems	Mechanical	Building automation system improvements	\$0				
Facilities	2	Building Systems	Mechanical	Replace air handling units	\$26,890				
Facilities	1	Building Systems	Plumbing	Plumbing Upgrade Allowance	\$3,215				
Facilities	1	Building Systems	Plumbing		\$0				
Facilities	1	Building Systems	Technology	Technology Upgrade Allowance	\$6,430				
Facilities	1	Building Systems	Technology	Technology Upgrade Allowance	\$0				
Facilities	3	Common Area Renovation	ADA	Toilet Room Renovations for ADA Compliance	\$30,864				
					Funded	Unfunded	Additional MP Work	Actual	NOTES
					\$150,000	\$100,000	\$0	\$0	\$250,000

TOTAL ALL PHASES





OVERALL ANALYSIS









"BUILDINGS HAVE GOOD BONES"













BOILER REPLACEMENT





FULL HVAC SYSTEM REPLACEMENT (EXCEPT PAC ADDITION)








POOL SETTLEMENT AND HVAC CONCERN
(F WING HEATING ONLY CREATING HUMIDITY












FLOODING IN CONNECTING LINK





AREA 1 PARKING LOT RESURFACING





B100 FIREPROOFING COMPROMISED



WINDOW REPLACEMENT (D100 & E100)
NON-THERMALLY BROKEN FRAMES



CARPET REPLACEMENT (B100, B200, D100, D200)

BETTENDORF MIDDLE SCHOOL







Gym RTU-2

REPLACE GYM ROOFTOP UNITS AND ADD DUCTWORK INSULATION

BETTENDORF MIDDLE SCHOOL







PARTIAL ROOF REPLACEMENT - (ORANGE); SEAM/FLASHING FAILURES, WET INSULATION



BETTENDORF MIDDLE SCHOOL



STRUCTURAL CONCERN AT WING WALL (4W, 5W & 6W)



EXHAUST AT LASER



WINDOW REPLACEMENT ORIGINAL BUILDING



CASEWORK
REPLACEMENT IN
SCIENCE AREAS






TOILET PARTITION REPLACEMENT




EDISON ACADEMY



ROOF EXHAUST DUCTWORK



EXTERIOR LIGHT REPLACEMENT



EGRESS AND FIRE RATING CONCERNS



EDISON ACADEMY







PARTIAL ROOF REPLACEMENT – (ORANGE); SEAM/FLASHING FAILURES, WET INSULATION



HERBERT HOOVER ELEMENTARY SCHOOL








SITE DRAINAGE ISSUE WITH RUNOFF EROSION



HERBERT HOOVER ELEMENTARY SCHOOL



PARTIAL ROOF REPLACEMENT – (RED & ORANGE)



- PLANT GROWTH ON ROOF
- INSULATION CUPPED MEANING WATER INFILTRATION
- INSULATION NOT SECURED
- ROOF CURRENTLY HELD BY FASTENING BAR



HERBERT HOOVER ELEMENTARY SCHOOL



SECURE ENTRANCE



CARPET REPLACEMENT ORIGINAL BUILDING




WINDOW REPLACEMENT (SINGLE PANE)
ORIGINAL BUILDING



GYM CEILING CONCERNS

MARK TWAIN ELEMENTARY SCHOOL



TUNNEL WATER INFILTRATION





BASEMENT WATER INFILTRATION CONCERN

MARK TWAIN ELEMENTARY SCHOOL



PARTIAL ROOF REPLACEMENT - (ORANGE). SEAM/FLASHING FAILURES WITH WET INSULATION





MARK TWAIN ELEMENTARY SCHOOL





CARPET AND LIGHT REPLACEMENT THROUGHOUT





INTERCOM AND BELL SYSTEM REPLACEMENT



SECURE ENTRANCE


PAUL NORTON ELEMENTARY SCHOOL





SECURE ENTRANCE UPGRADES








EXTERIOR HOLLOW METAL FRAME REPLACEMENT AT MAIN ENTRANCE

PAUL NORTON ELEMENTARY SCHOOL



CARPET REPLACEMENT



SATURATED CEILING



PLUG MOLD BY SINK DATED CASEWORK





TOILET ROOM
TILE REPLACEMENT


THOMAS JEFFERSON ELEMENTARY SCHOOL











FULL ROOF REPLACEMENT



THOMAS JEFFERSON ELEMENTARY SCHOOL



GYM CEILING CONCERNS



NEW SECURE ENTRANCE



KITCHEN UPGRADES

THOMAS JEFFERSON ELEMENTARY SCHOOL



WINDOW AND SOFFIT REPLACEMENT



STORAGE/ELECTRICAL ROOM FIRE RATING CONCERNS

SUMMARY

BUILDING "BONES" ARE IN GOOD SHAPE.

POTENTIAL PRIORITIES:

- HIGH SCHOOL HVAC ~\$3M TO \$5M.
- MIDDLE SCHOOL GYM HVAC ~\$700K
- MARK TWAIN TUNNELS TBD
- THOMAS JEFFERSON ROOFING/SOFFITS ~\$425K
- SECURE ENTRANCES (T.J., NORTON, TWAIN, HOOVER) TBD
- HIGH SCHOOL POOL SETTLEMENT TBD
- HIGH SCHOOL EXTERIOR TUNNEL FLOODING ~\$100K
- PARTIAL ROOF REPLACEMENTS (HOOVER, EDISON, MS, HS) ~\$800K





NEXT STEPS

- CONFIRM FACILITY ASSESSMENT BUDGET ITEMS PER SCHOOL IN CONJUNCTION WITH ESTES CONSTRUCTION.
- MEET WITH DISTRICT ADMINISTRATORS TO PRIORITIZE POTENTIAL DISTRICT IMPROVEMENTS. (8/29/17)
- COLLABORATE WITH DISTRICT TO IDENTIFY POTENTIAL BUDGET FOR ALL LONG TERM FACILITY PROJECTS.
- COLLABORATE WITH DISTRICT TO PRIORITIZE FACILITY AND POTENTIAL DISTRICT IMPROVEMENTS.





QUESTIONS



